Attachment "F" – Rubber Gasket



The Rotunda (OE) VCM has a rubber gasket under the plastic cover. Some of the non-genuine units do not have this gasket.